



INFO SERVICE BULLETIN No. 08

to all distributors, owners

Information regarding replacements of Wheel Brake Assembly

INFORMATION ONLY

Please pay attention to the following safety definitions used in this service bulletin:

WARNING! Disregarding the following instruction leads to severe deterioration of flight safety and hazardous situations, including such resulting in serious injury and loss of life.

CAUTION! Disregarding the following instruction leads to serious deterioration of flight safety, may cause serious damage to the aircraft and suspend warranty.

Applies to all Sinus/Virus aircraft up to SN 240.

Distributors are to translate this service bulletin into their native language and forward it to all concerned owners in your area immediately.

Please see following page(s) for further details.


Information regarding replacements of Wheel Brake Assembly

Required actions upon replacement

Upon replacement of Wheel Brake Assembly, it is necessary to replace both brake pads and brake discs. The reason for this is that new brake pads are not compatible with old brake discs and vice versa. When ordering individual parts from Pipistrel d.o.o. Ajdovscina, make sure you order according to the below part numbers of the individual components of the wheel brake assembly. This is to ensure problem-free operation.

7267 Wheel brake disc

7274 Wheel brake pad



WARNING! Should the incorrect combination of brake discs and pads be used, braking action may be deteriorated greatly.

Distributors

As a distributor you are to advise each concerned owner about this topic.

Pipistrel d.o.o. Ajdovscina
Ivo Boscarol, GM

THIS IS THE END OF THE SERVICE BULLETIN.
Please confirm reception by e-mail: info@pipistrel.si