 PIPISTREL DOA No.: EASA.21J.524P	SERVICE BULLETIN		Bulletin Number
			SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	ALPHA Trainer Application of interior and exterior placards		Issue No. 2
			Supersedes Bulletin Number
			Issue No. 1
			Page 1 of 9
Aircraft make	Aircraft model	Affected serial numbers	
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register	
Date of release	Date of effect	Date of required corrective action	
9 September 2013	9 September 2013	9 September 2013 or before next flight	

1. COMPLIANCE

Mandatory: Pipistrel considers this Alert Service Bulletin to be MANDATORY Time scope: Accomplish the task before next flight. Compliance time begins upon receipt of this Service Bulletin.

Note: Pipistrel's Alert is subject to ASTM 2295 specifications and requirements for Light Sport Aircraft.

2. EFFECTIVITY

Aircraft serial numbers:
All ALPHA Trainer aircraft registered in the USA under the FAA LSA register.

3. AGENCY APPROVAL

N/A

4. PURPOSE

The purpose of this Service Bulletin is to notify owners to verify accurate application of interior and exterior placards.

5. DESCRIPTION


It has been reported that certain ALPHA Trainer aircraft reached their port of destination in the USA with placards missing. Accurate placarding must therefore be verified especially in the critical areas such as Fuel Quantity, etc. In addition, newly supplied placards comply with FAA Advisory Circular AC45-5 of 11/16/2012 about placarding rules for S-LSA and E-LSA.

6. WARRANTY INFORMATION

The placards are provided free of charge.

7. PERSONNEL REQUIREMENTS

N/A

 PIPISTREL DOA No.: EASA.21J.524P	SERVICE BULLETIN		Bulletin Number
			SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	ALPHA Trainer Application of interior and exterior placards		Issue No. 2
			Supersedes Bulletin Number
			Issue No. 1
			Page 2 of 9
Aircraft make	Aircraft model	Affected serial numbers	
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register	
Date of release	Date of effect	Date of required corrective action	
9 September 2013	9 September 2013	9 September 2013 or before next flight	

8. OTHER PUBLICATION

None.

9. WEIGHT AND BALANCE

Not Affected


10. MATERIAL INFORMATION

All material provided free of charge.


11. ACCOMPLISHMENT INSTRUCTIONS

A set of placards (PN: 1111083_ALPHA_TRAINER) was supplied to each ALPHA Trainer owner. The set of placard contains two sheets, one for exterior placards (white background), and one for interior placards.

See next pages for placard identification and placement.

 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 3 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight

INTERIOR PLACARDS




 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 4 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight



Figure 1.: Location 1-N



Figure 2.: Location 2-N



Figure 3.: Location 3-N



Figure 4.: Location 4-N


 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 5 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight



Figure 5.: Location 13-N




Figure 6.: Location 5-N




Figure 7.: Location 6-N_L/D



Figure 8.: Location 7-N

 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 6 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight

EXTERIOR PLACARDS




 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 7 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight



Figure 1.: Location 1-Z



Figure 2.: Location 2-Z



Figure 3.: Location 3-Z



Figure 4.: Location 4-Z_L/D


 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 8 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight



Figure 5.: Location 5-Z



Figure 6.: Location 6-Z_L/D



Figure 7.: Location 7-Z in Location 8-Z



Figure 8.: Location 9-Z


 PIPISTREL DOA No.: EASA.21J.524P	<h1>SERVICE BULLETIN</h1>	Bulletin Number
		SB-125-13-01
Pipistrel LSA s.r.l. Via Aquileia 75 34170 Gorizia, Italy, EU www.pipistrel.eu Phone: 0481 522000	<h2>ALPHA Trainer</h2> Application of interior and exterior placards	Issue No. 2
		Supersedes Bulletin Number
		Issue No. 1
		Page 9 of 9
Aircraft make	Aircraft model	Affected serial numbers
PIPISTREL	ALPHA	ALL ALPHA Trainer aircraft on the USA FAA register
Date of release	Date of effect	Date of required corrective action
9 September 2013	9 September 2013	9 September 2013 or before next flight



Figure 9.: Location 10-Z_L/D



Figure 10.: Location 11-M



Figure 11.: Location 12-M

An appropriate entry that the aircraft has been replacarded according to this Service Bulletin must be made in maintenance record.

END OF SERVICE BULLETIN.